# Maryland Historical Trust

Maryland Inventory of Historic Properties number:

Name: 115 6	ver Amir	ZAK
Historic Bridge Inventory, and S.	HA provided the Trust wit	yland State Highway Administration as part of the vith eligibility determinations in February 2001. 13, 2001. The bridge received the following
Eligibility Recommended	MARYLAND HISTOR	PRICAL TRUST  Eligibility Not RecommendedX
Criteria:ABC Comments:	D Considerations:	ABCDEFGNone
Reviewer, OPS:_Anne E. Bruder Reviewer, NR Program:Peter I		Date:3 April 2001 Date:3 April 2001

of de

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. <u>HA-1978</u>

SHA Bridge No. 12058-3 and 12058-4 Bridge name MD 715 over AMTRAK
LOCATION: Street/Road name and number [facility carried] MD 715 (Short Lane)
City/town Aberdeen Vicinity X
County Harford
This bridge projects over: Road Railway_X Water Land
Ownership: State X County Municipal Other
HISTORIC STATUS:  Is the bridge located within a designated historic district? Yes NoX
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete
Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder X :  Rolled Girder _ X :  Plate Girder :  Rolled Girder Concrete Encased :  Plate Girder :
Metal Suspension
Metal Arch
Metal Cantilever
Concrete: Concrete Arch: Concrete Slab Concrete Beam Rigid Frame Other Type Name

HA-1978

DESCRI	PTION:			
Setting:	Urban	X	Small town	Rural
Describe	Setting:			

Bridge No. 12058 carries eastbound and westbound MD 715 (Short Lane) over AMTRAK in Harford County. MD 715 runs east-west and AMTRAK runs north-south. The bridge is located in the vicinity of Aberdeen, and is bordered by the Aberdeen Proving Ground to the south.

## **Describe Superstructure and Substructure:**

Bridge No. 12058 is a dual structure carrying eastbound and westbound MD 715. Each structure is a 3-span, 2-lane, metal girder bridge. The bridge was originally built in 1943, and the deck, parapets, and two (2) girders were replaced in 1983. Each structure is 179 feet, 6 inches long and the clear roadway width of each structure is 24 feet. The out-to-out width of each structure is approximately 40 feet. The superstructure for both structures is the same, consisting of eight (8) rolled girders, which support a concrete deck and concrete parapets. The roadway is carried on the girders and the concrete deck has a bituminous wearing surface. The bridge has solid concrete parapets and the roadway approaches have steel guard rails. A date impression on the parapet indicates that the bridge was constructed in 1943 and was rehabilitated in 1983. The substructure consists of two (2) concrete abutments and two (2) concrete piers on each structure. The bridge has a sufficiency rating of 98.4.

According to the 1995 inspection report, this structure was in satisfactory condition with areas of light rust and peeling paint on the girders. The concrete deck and abutments have fine vertical cracks and the concrete piers have vertical, horizontal and longitudinal cracks with delamination and the potential for spalling. The concrete parapets have minor shrinkage cracks and water stains.

## **Discuss Major Alterations:**

In 1983, the bridge deck was replaced, new bearings were installed and two (2) exterior girders were replaced. The remaining girders were temporarily removed in order to reconstruct the top portions of the substructure at that time, but were reset.

#### **HISTORY:**

WHEN was the bridge built: 1943	_
This date is: Actual X	Estimated
Source of date: Plaque X Design plans	County bridge files/inspection form
Other (specify): State Highway Administration by	ridge files/inspection forms

# WHY was the bridge built?

The bridge was constructed to provide access over the railroad at the entrance to the Aberdeen Proving Ground. The Proving Ground, which was established in 1917, experienced continuous expansion throughout the early twentieth century. By 1943, the railway branch at the Proving Ground and the adjacent Pennsylvania Railroad had expanded to meet the increasing needs of Ordinance personnel and facilities developing more advanced weapons. Under the Defense Highway Act of 1941, which provided funding for the construction of roads leading to war plants and military installations, the grade separation at the access road (Short Lane) to the Aberdeen Proving Ground was constructed. The traffic bottleneck at the Pennsylvania Railroad (AMTRAK) crossing was

reportedly eased when the new above-grade access road to U.S. 40 and Bridge 12058 opened to vehicular traffic in October 1943 (Harford 1953, 58-59 and State Roads Commission 1958, 153).

WHO was the design	er:
WHO was the design	er:

Unknown

WHO was the builder?

Unknown

WHY was the bridge altered?

The bridge was altered to correct functional or structural deficiencies.

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

# **SURVEYOR/HISTORIAN ANALYSIS:**

This bridge may have Nationa	al Register signific	ance for its association with:
A - Events	B- Person	
C- Engineering/archite	ectural character _	

The bridge does not have National Register significance.

#### Was the bridge constructed in response to significant events in Maryland or local history?

Metal girder bridges were most likely introduced and first popularized in Maryland by the state's major railroads of the nineteenth century including the Baltimore and Susquehanna, its successor the Northern Central, and the Baltimore and Ohio Railroad. Bridge engineering historians have documented the fact that James Milholland (or Mulholland) erected the earliest plate girder span in the United States on the Baltimore and Susquehanna Railroad in 1846 at Bolton Station, near present-day Mount Royal Station. The sides (web) and bottom flange of Milholland's 54-foot-long span were wholly of wrought iron and included a top flange reinforced with a 12x12-inch timber. Plates employed in the bridge were 6 feet deep and 38 inches wide, giving the entire bridge a total weight of some 14 tons. Milholland's pioneering plate girder cost \$2,200 (Tyrrell 1911:195). By December 31, 1861, the Northern Central Railroad, which succeeded the Baltimore and Susquehanna, maintained an operating inventory in Maryland of 50 or more bridges described simply as "girder" spans, in addition to a number of Howe trusses. Most of these were probably iron girder bridges; the longest were the 117-foot double-span bridge over Jones Falls and the 106-foot double-span girder bridge at Pierce's Mill (Gunnarson 1990:179-180).

As in the nation, girder bridge technology in Maryland was quickly adapted to cope with the increasingly heavy traffic demands of the twentieth century caused by automobile and truck traffic. The 1899 Maryland Geological Survey report on highways noted that "there are comparatively few I-beam bridges, one of the cheapest and best forms for spans less than 25 or 30 feet" (Johnson 1899:206). Interestingly, the report also urged construction of a composite metal, brick, and concrete bridge, noting that "no method of construction is more durable than the combination of masonry and I-beams, between which are transverse arches of brick, the whole covered with concrete, over which

H17-1978

is laid the roadway" (Johnson 1899:206). Whether any such bridges (transitional structures between I-beams and reinforced concrete spans) were built is unknown.

Official state and county highway reports—issued between 1900 and the early 1920s through the Highway Division of the Maryland Geological Survey and its successor, the State Roads Commission—generally do not reference or describe girder construction. An analysis of the current statewide listing of county and municipal bridges (a listing maintained by the State Highway Administration) reveals that 48 county bridges, out of the total of 141 approximately dated to "1900" by county engineers, were listed as steel girder, steel stringer, or variants of such terms. (It should be noted that the "1900" date is often given when no exact date is pinpointed for a bridge that is clearly old). A grand total of 200 bridges (including "steel culverts"), out of 550 bridges dated on the county list between 1901 and 1930, were described as steel beam, steel girder, or steel stringer and girder varieties. The total suggests that among the various highway bridge types built in the early twentieth century metal girder bridges in Maryland between 1900 and 1930 were second in popularity only to reinforced concrete bridges. However, these numbers must be interpreted with caution, as they do not necessarily include all county and municipal bridges.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

# Is the bridge a significant example of its type?

A significant example of a metal girder bridge should possess character-defining elements of its type, and be readily recognizable as an historic structure from the perspective of the traveler. The integrity of distinctive features visible from the roadway approach, including parapet walls or railings, is important in structures which are common examples of their type. In addition, the structure must be in excellent condition. This bridge, which lacks such features as the original deck and parapets, and has two (2) girders which have been replaced, is an undistinguished example of a metal girder bridge.

## Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains some of the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including rolled girders, concrete abutments, and concrete piers, however alterations to the structures in 1983 resulted in the loss of such distinctive features as two (2) of the original girders and the original parapets.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?


This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.


Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

BIB	LI	o	GR	AP	Ή	Y:

County inspection/bridge files SHA inspection/bridge files X Other (list):
Gunnarson, Robert 1990 The Story of the Northern Central Railway, From Baltimore to Lake Ontario. Greenberg Publishing Co., Sykesville, Maryland.
Harford County Directory 1953 State Directories Publishing Company, Baltimore, Maryland.
Johnson, Arthur Newhall  1899 The Present Condition of Maryland Highways. In Report on the Highways of Maryland.  Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.
State Roads Commission 1958 A History of Road Building in Maryland. Published by author, Baltimore.
Tyrrell, Henry G. 1911 History of Bridge Engineering. Published by author, Chicago.
SURVEYOR:
Date bridge recorded2/25/97
Name of surveyor Caroline Hall
Organization/Address P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number (410) 296-1685 FAX number (410) 296-1670





1. HA-1978 2. MD 715 Over ALTRAL 3. HARFORD CO, MO 4 Caroline Hall 5 3 47 4. MDSHPD 7. detail of substructure (NB 8.136



1. 148-1978 2. MO 715 over AMTRAZ 3. Harfold Co, MO 4. Caroline Hall 5.3/97 6. MDSHPD 7. West side (NB) 8.2957



1. HA-1978 2. MD 715 over AMERICA 3. Harford Co, MD 4 Caroline wall 5.3/97 6. MD541PD 1 east side (SB) 8.3017



1. HA-1978 2. MD 715 over Am PAY 3. Harford Cu, MD 4. Caroline Hell 5,3/97 6 MDSHPD 7. Mast le roadway up ouch (NB) 8.4017



1. HA-1978 2. MD 715 Over AMPRAY 3. Harford Co MI) 4. Caroline ball 5, 3/97 6 MDSHPO 7 last side (NB) approach (NB 8.5017



1. HA-1978 2. MD 715 OVER AMTRAY 3. Harford Co, MD 4 Caroline Hall 5. 3/9.7 6. MDSHPO 1. west side (SB)

8.6017



1 HA-1978 2. ND 715 over AMEAN 3. Harford Co, MD 4. Caroline Hall 5.3/97 6 MDSHPO 7. both structures

8.7017